

What to do if the software update is unsuccessful...

Octalarm-TOUCH | Octalarm-TOUCH pro

It is possible that a software update is sent to your Octalarm-Touch alarm dialler with important additions that further increase the safety and user-friendliness of the dialler. Is the update not successful for you even though you have tried to implement the software update? Reset the detector and within a few minutes you can still use the latest software with the additional functions.

Arranged in 15 minutes

- Raise the housing cover until you hear a click.
- Press the white button next to the battery (PWR-OFF) and keep it pressed for a few seconds until the Octalarm-Touch restarts.

! Keep in mind that there is no alarm in these few seconds.

- Wait 10 minutes after the Octalarm-Touch has started up.
- Press the message "Software update, Update available ..." again to go to the update menu
- Make the new update. It now takes about 15 seconds for the update to be installed and the Octalarm-Touch to restart.

